

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG.7




FIG.8




FIG.9




FIG.10




FIG.11




FIG.12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 19




FIG. 18




FIG. 21




FIG. 20




FIG. 22




FIG.24




FIG.23




FIG.26




FIG.25




FIG.27




FIG. 28





FIG. 31

FIG. 30






FIG. 32








FIG. 34








FIG.38




FIG.39




FIG.40




FIG.41




FIG.42




FIG.43




FIG.44




FIG.45




FIG.46




FIG.47




FIG.48




FIG.49




FIG.50




FIG.51




FIG.52A




FIG.52B




FIG.52C




FIG.52D

HEART LIFTED




FIG.52E





FIG.52F





[illegible][illegible]

FIG.52I





FIG.52J

PULMONARY ARTERY



FIG.52K



4004536 4004536




FIG. 53B




FIG. 54




FIG. 55




FIG. 56




FIG. 57




FIG. 58A




FIG. 58B




FIG. 58C




FIG. 58D




FIG. 58E




FIG. 58F




FIG. 58G




FIG. 59




FIG. 60A




FIG. 60B




FIG. 60C




FIG. 60D




FIG. 60E




FIG. 60F




FIG. 60G




FIG. 60H






FIG. 60I








FIG. 61C





FIG. 61D







FIG. 61H






FIG. 61I




FIG. 617

FIG.62A




FIG.62B




FIG.62C




FIG. 62D




FIG. 62E




FIG. 62F




FIG. 62G




FIG. 62H





FIG. 62I









FIG. 66





FIG. 67






FIG. 68

404666 43001







FIG. 69






FIG. 73

FIG 74




FIG. 75




FIG. 76





FIG. 77






FIG. 78




FIG. 79




FIG. 80




FIG. 81




FIG 83




Fig. 83




Fig. 83A




FIG. 84

Fig. 5.

FIG. 86




FIG. 86




FIG. 87




FIG. 88




FIG. 89




FIG. 90

FIG. 92





FIG. 92

X






FIG. 94




FIG. 95




FIG. 96




FIG. 97

X




FIG. 98




FIG. 99

X

FIG. 100




FIG. 101